

REQUIRED TOOLS/CLOTHING

- ☐ 12" Adjustable wrench
- ☐ Antivibe Hammer – straight claw - 22 oz. minimum (*Granite Falls students*)
- ☐ Hammer – straight claw - 22 oz. (*Jackson students*)
- ☐ Fiber glass folding ruler
- ☐ 10" Adjustable wrench
- ☐ Folding skinning knife
- ☐ Lineman working gloves
- ☐ 9" Klein side cutters
- ☐ Demolition Screw Driver 7" shank
- ☐ Safety glasses ANSI Z87.1 standard
- ☐ Hard Hat ANSI Z89.1 standard with chin strap
- ☐ Lineman or Logger boots

OPTIONAL TOOLS/CLOTHING

- ☐ Ratchet or speed wrenches $\frac{1}{2}$, $\frac{9}{16}$, $\frac{5}{8}$, $\frac{11}{16}$, $\frac{3}{4}$, $\frac{7}{8}$
- ☐ 8" channel lock WIDEAZZ adjustable wrench
- ☐ 12" Lowell Lineman wrench
- ☐ 12" Channel Lock or pump pliers
- ☐ Winter work coat and bibs
- ☐ Hard hat liner

REQUIRED CLIMBING GEAR

- ☐ Top and bottom nylon straps
- ☐ Gaff Guards
- ☐ Climbers (Hooks)
- ☐ Climber pads
- ☐ Climbing belt
- ☐ Tool or Equipment bag
- ☐ Tool holder for belt (4 pouch recommended)
- ☐ Fall arrest protection
- ☐ Ditty bag or nut and bolt bag
- ☐ Adjustable secondary lanyard

Powerline Faculty

Brian.Binnebose@mnwest.edu | Doug.Schuett@mnwest.edu | Eric.Stoll@mnwest.edu